



SUZUKI

SUZUKI



 Code 

**0-9**  
 8HY ..... 1218  
 9HX ..... 1220

**A**  
 AB51 ..... 1212



**D**  
 D13A ..... 1214

**F**  
 F10A ..... 1212  
 F8A ..... 1212  
 F8B ..... 1212

 Code 

**G**  
 G10 ..... 1212  
 G10A ..... 1212  
 G10 Turbo ..... 1212  
 G13A ..... 1214  
 G13B ..... 1216  
 G13B (8V) ..... 1214  
 G13BA ..... 1216  
 G13BB ..... 1216  
 G16A ..... 1218  
 G16B ..... 1218  
 G16K-C ..... 1218  
 G18 ..... 1220

**H**  
 H 20 A ..... 1222  
 H 25 A ..... 1226



 Code 

H 27 A ..... 1226

**J**  
 J18A ..... 1220  
 J20A ..... 1222

**K**  
 K10A ..... 1214  
 K10B ..... 1214  
 K12A ..... 1214  
 K12B ..... 1214  
 K9K 700 ..... 1218

**M**  
 M13A ..... 1216  
 M13A WT ..... 1216  
 M15A ..... 1218

 Code 

M16A ..... 1220


**R**  
 RF ..... 1222  
 RHW ..... 1224  
 RHZ ..... 1224

**X**  
 XUD9 ..... 1220  
 XUD9A ..... 1220  
 XUD9SD ..... 1222  
 XUD9TE ..... 1224

**Z**  
 Z13DT ..... 1214

 Code 

 Code 

 Code 

 Code 

SUZUKI						
Ltr.						
0,8 AB51 F8B	29 kW (39 PS) ALTO	06/82-12/85	<b>D80940-00</b> 11100-78830	<b>H80940-00</b> 11141-78402 68,7 Ø		
0,8 AB51	29 kW (39 PS) ALTO	01/86-11/93	<b>S80940-00</b> ⑫ ⑬ 11400-84824 <b>D80940-01</b> ⑫ 11400-84824 HS	<b>H80940-00</b> 11141-78402 68,7 Ø		
0,8 F8A	27-29 kW (37-39 PS) ALTO CARRY LJ 80	01/80-12/85		<b>H80941-00</b> 11141-73002 64 Ø		
1,0 F10A	30-33 kW (41-45 PS) SAMURAI SJ 410 SUPER CARRY	09/81→	<b>S80904-01</b> ⑫ ⑬ 11400-85820 <b>D80904-01</b> ⑫ 11100-85820	<b>H80904-10</b> 11141-75102 67 Ø		
1,0 G10 G10 Turbo	37-52 kW (50-71 PS) SWIFT	10/83-12/89	<b>S37215-00</b> ⑫ ⑬ 11400-82814 <b>D37215-00</b> ⑫ 11100-82814	<b>H40367-00</b> 11141-82001 75,2 Ø		
1,0 G10A	37-40 kW (50-54 PS) SWIFT	10/83-05/01	<b>S40013-00</b> ⑫ ⑬ <b>D40013-00</b> ⑫	<b>H40013-00</b> 75 Ø		



<b>X83230-01</b> 11189-78100	<b>N93015-00</b> 09289-070005-000 (6x)		<b>X82170-01</b> 14140-78100	<b>X54890-01</b> 11529-79110	<b>P77582-01 K</b> ← 09283-32016 32x47x8 A SL RD NBR <b>P77503-01 K</b> → 09283-60003 60x80x8 A SL LD MVQ <b>P77582-01 N</b> 09283-32016 32x47x8 A SL RD NBR
	<b>N93015-00</b> 09289-070005-000 (6x)		<b>X82170-01</b> 14140-78100	<b>X54890-01</b> 11529-79110	<b>P77582-01 K</b> ← 09283-32016 32x47x8 A SL RD NBR <b>P77503-01 K</b> → 09283-60003 60x80x8 A SL LD MVQ <b>P77582-01 N</b> 09283-32016 32x47x8 A SL RD NBR
<b>X83202-01</b> 11189-73001	<b>N93015-01</b> 09289-070005-000 (8x)	<b>X89615-01</b> 2x 13119-73000	<b>X82142-01</b> 14140-73001	<b>X54869-01</b> 11529-73001	<b>P77582-01 K</b> ← 09283-32016 32x47x8 A SL RD NBR <b>P77503-01 K</b> → 09283-60003 60x80x8 A SL LD MVQ <b>P77582-01 N</b> 09283-32016 32x47x8 A SL RD NBR
<b>X83202-01</b> 11189-73001	<b>N93015-01</b> 09289-070005-000 (8x)	<b>X89615-01</b> 2x 13119-73000	<b>X82142-01</b> 14140-73001	<b>X54889-01</b> 11529-80000	<b>P77582-01 K</b> ← 09283-32016 32x47x8 A SL RD NBR <b>P77503-01 K</b> → 09283-60003 60x80x8 A SL LD MVQ <b>P77582-01 N</b> 09283-32016 32x47x8 A SL RD NBR
<b>X83373-01</b> 11189-82000	<b>N93015-00</b> 09289-070005-000 (6x)		<b>X82372-01</b> 14140-82000	<b>731414</b> 	
<b>X83268-01</b>	<b>N90112-01</b> 09289-05012-000 (6x)	<b>X89706-01</b>	<b>X82228-01</b>	<b>731414</b> 	<b>P77581-01 K</b> ← 09283-32026 32x47x6 A SL RD MVQ <b>P77505-01 K</b> → 09283-68001 68x86x8 A SL LD MVQ <b>P77581-01 N</b> 09283-32026 32x47x6 A SL RD MVQ



SUZUKI

SUZUKI						
Ltr.						
1,0 K10A	48 kW (65 PS)	WAGON R+	02/98-05/00	<b>D40039-00</b> <sup>12</sup> 11401-75812-000	<b>H40039-00</b> 11141-75F10-000 MLS 	
1,0 K10B	48-50 kW (65-68 PS)	WAGON R+	01/08→	<b>D38090-00</b> <sup>12</sup>	<b>H40476-00</b> 11141-51K00 MLS 	<b>T50156-00</b> 117-69J00 (8x)
1,2 K12A	51 kW (69 PS)	WAGON R+	02/98-05/00	<b>D40046-00</b> <sup>12</sup>	<b>H40046-00</b> 11141-75F30-000 MLS 	
1,2 K12B	63 kW (86 PS)	SPLASH	01/08→	<b>D38091-00</b> <sup>12</sup>	<b>H40477-00</b> 11141-73K00 MLS 	<b>T50157-00</b> 117-69J00 (10x)
1,3 D13A Z13DT	51-55 kW (69-75 PS)	IGNIS SPLASH CDTI SWIFT WAGON R+	09/03→	<b>D36649-00</b> <sup>12</sup>  <b>B36649-00</b> 	<b>H08120-00</b> 0,72 mm MLS <b>H18120-10</b> 0,82 mm 1 MLS <b>H28120-20</b> 0,92 mm 2 MLS 	<b>T08128-00</b>  RIBE
1,3 G13A	44-54 kW (60-73 PS)	SAMURAI SJ 413 SWIFT	09/84→	<b>S80942-00</b> <sup>12 13</sup> 11400-82826 <b>D80942-00</b> <sup>12</sup> 11100-82826	<b>H80942-00</b> 11141-82611 75,2 Ø 	
1,3 G13A G13B (8V)	47 kW (64 PS)	SAMURAI	11/88→	<b>S80942-02</b> <sup>12 13</sup> 11400-61880 <b>D80942-02</b> <sup>12</sup> 11100-61820	<b>H80942-00</b> 11141-82611 75,2 Ø 	

<sup>12</sup> junta, carcasa de colector de admisión / Dichtung Ansaugkrümmergehäuse / gasket, intake manifold housing / joint d'étanchéité, carter de collecteur d'admission / guarnizione, alloggiam. collettore aspirazione / прокладка, корпус впускного коллектора



<b>X83284-01</b> 11189-75F01-000 	<b>N93034-00</b> 09289-05012-000 (16x)	<b>X89728-01</b> 13119-75F00-000 	<b>X82250-01</b> 14141-75F00-000 	<b>731414</b> 	
<b>X83371-01</b> 11189-51K00 	<b>N93134-00</b>	<b>X89890-01</b> 13119-51K00  <b>X89853-01</b> <sup>10</sup> 13118-51K00 	<b>X82373-01</b> 14140-51K00 	<b>731414</b> 	<b>P77453-01 K</b> ← 09283-41001 41x53x6 FPM <b>P77679-01 K</b> → 09283-83002 83x97x7 LD FPM/ACM
<b>X83284-01</b> 11189-75F01-000 	<b>N93034-00</b> 09289-05012-000 (16x)	<b>X89728-01</b> 13119-75F00-000 	<b>X82250-01</b> 14141-75F00-000 	<b>731414</b> 	
<b>X83370-01</b> 11189-73K00 	<b>N93135-00</b>	<b>X89891-01</b>  <b>X89854-01</b> <sup>10</sup> 13118-73K00 	<b>X82374-01</b> 14140-73K01 	<b>731414</b> 	<b>P77453-01 K</b> ← 09283-41001 41x53x6 FPM <b>P77679-01 K</b> → 09283-83002 83x97x7 LD FPM/ACM
<b>X83008-01</b> 	<b>N92990-00</b> <b>P76662-00</b> 16x	<b>X87558-01</b> 	<b>X81490-01</b> 	<b>731414</b> 	<b>P77355-01 K</b> ← 40x52x7 AB SL RD FPM/ACM <b>P77340-01 K</b> → 78x100x9 A SL LD PTFE
<b>X83231-01</b> 11189-82600 	<b>N93015-01</b> 09289-070005-000 (8x)	<b>X89644-01</b> 13119-62601 	<b>X82169-01</b> 14141-63B00 	<b>X54891-01</b> 11510-82600 	<b>P77581-01 K</b> ← 09283-32026 32x47x6 A SL RD MVQ <b>P77505-01 K</b> → 09283-68001 68x86x8 A SL LD MVQ <b>P77582-01 N</b> 09283-32016 32x47x8 A SL RD NBR
<b>X83231-01</b> 11189-82600 	<b>N93015-01</b> 09289-070005-000 (8x)	<b>X89643-01</b> 13119-63B00 	<b>X82169-01</b> 14141-63B00 	<b>X54891-01</b> 11510-82600 	<b>P77581-01 K</b> ← 09283-32026 32x47x6 A SL RD MVQ <b>P77505-01 K</b> → 09283-68001 68x86x8 A SL LD MVQ <b>P77582-01 N</b> 09283-32016 32x47x8 A SL RD NBR



SUZUKI

SUZUKI						
Ltr.						
1,3 G13B G13BA	50-74 kW (68-101 PS) BALENO SAMURAI SWIFT	11/88→	<b>S80942-03</b> ⑫ ⑬ 11400-61852 <b>D80942-03</b> ⑫ 11100-61841	<b>H80942-00</b> 11141-82611 75,2 Ø 		
1,3 G13B	74 kW (101 PS) SWIFT	08/85-03/89	<b>S80942-01</b> ⑫ ⑬ 11400-86822 <b>D80942-01</b> ⑫ 11100-86822	<b>H80942-00</b> 11141-82611 75,2 Ø 		
1,3 G13BB	56-63 kW (76-86 PS) ALTO BALENO CARRY GRAND VITARA JIMNY SWIFT WAGON R+	03/97→	<b>S40079-00</b> ⑫ ⑬ 11402-61862-000 <b>D40079-00</b> ⑫	<b>H40079-00</b> 11141-86502-000 75 Ø 		
1,3 M13A	60-69 kW (82-94 PS) GRAND VITARA IGNIS JIMNY LIANA SWIFT WAGON R+	09/00→	<b>D36974-00</b> ⑫ 11400-86873	<b>H80735-00</b> 11141-69G03 MLS 		
1,3 M13A VVT	69 kW (94 PS) IGNIS	09/03→	<b>D36974-01</b> ⑫ 11400-69853	<b>H80735-00</b> 11141-69G03 MLS 		

⑩ junta, carcasa de colector de admisión / Dichtung Ansaugkrümmergehäuse / gasket, intake manifold housing / joint d'étanchéité, carter de collecteur d'admission /  
guarnizione, alloggiam. collettore aspirazione / прокладка, корпус впускного коллектора



<b>X83232-01</b> 11189-86500 	<b>N90112-00</b> 09289-05012-000 (16x)	<b>X89958-01</b> 13119-64B00 	<b>X82375-01</b> 14141-64B00 	<b>731414</b> 	<b>P77581-01 K</b> ← 09283-32026 32x47x6 A SL RD MVQ <b>P77505-01 K</b> → 09283-68001 68x86x8 A SL LD MVQ <b>P77582-01 N</b> 09283-32016 32x47x8 A SL RD NBR
<b>X83232-01</b> 11189-86500 	<b>N90112-00</b> 09289-05012-000 (16x)	<b>X89644-01</b> 13119-62601 	<b>X82169-01</b> 14141-63B00 	<b>731414</b> 	<b>P77581-01 K</b> ← 09283-32026 32x47x6 A SL RD MVQ <b>P77505-01 K</b> → 09283-68001 68x86x8 A SL LD MVQ <b>P77582-01 N</b> 09283-32016 32x47x8 A SL RD NBR
<b>X83269-01</b> 	<b>N90112-00</b> 09289-05012-000 (16x)	<b>X89830-01</b> ⑩ 	<b>X82229-01</b> 14140-52G00-000 	<b>731414</b> 	<b>P77581-01 K</b> ← 09283-32026 32x47x6 A SL RD MVQ <b>P77505-01 K</b> → 09283-68001 68x86x8 A SL LD MVQ <b>P77581-01 N</b> 09283-32026 32x47x6 A SL RD MVQ
<b>X83316-01</b> 11189-54GE0 	<b>N90112-00</b> 09289-05012-000 (16x)	<b>X89959-01</b> 13119-86G00 	<b>X81988-01</b> 14140-69G01 	<b>731414</b> 	<b>P77453-01 K</b> ← 09283-41001 41x53x6 FPM <b>P77454-01 K</b> → 09283-83001 83,5x103x8 FPM
<b>X83129-01</b> 11189-54G00 	<b>N90112-00</b> 09289-05012-000 (16x)	<b>X89779-01</b> 13119-69G00 	<b>X81988-01</b> 14140-69G01 	<b>731414</b> 	<b>P77453-01 K</b> ← 09283-41001 41x53x6 FPM <b>P77454-01 K</b> → 09283-83001 83,5x103x8 FPM



SUZUKI						
Ltr.						
1,4 8HY	66 kW (90 PS)	LIANA	03/05→	<b>S36724-00</b> <sup>12</sup> <sup>13</sup>  <b>D36724-00</b> <sup>12</sup>  <b>B36724-00</b> <sup>13</sup>	<b>H08129-00</b> 1,2 mm 2 MLS <b>H08129-10</b> 1,3 mm 3 MLS <b>H08129-20</b> 1,35 mm 1 MLS <b>H18129-30</b> 1,4 mm 4 MLS <b>H18129-40</b> 1,45 mm 5 MLS 	<b>T08130-00</b> 
1,5 K9K 700	48 kW (65 PS)	JIMNY	12/03→	<b>D36520-00</b> <sup>12</sup> → 040519 <b>D37078-00</b> <sup>12</sup> → 040520→ <b>B36520-00</b> <sup>13</sup> → 040329 <b>B37078-00</b> <sup>13</sup> → 040330→	<b>H80363-00</b> 0,6 mm MLS → 040519  <b>H80740-00</b> 0,7 mm MLS → 040520→	<b>T80363-00</b> 
1,5 M15A	73-80 kW (99-109 PS)	IGNIS SWIFT SX4	09/03→	<b>D36974-00</b> <sup>12</sup> 11400-86873	<b>H80735-00</b> 11141-69G03 MLS 	
1,6 G16A G16K-C	59-60 kW (80-82 PS)	VITARA	07/88-03/98	<b>S80959-00</b> <sup>12</sup> <sup>13</sup> 11400-60821 <b>D80959-00</b> <sup>12</sup> 11100-60811	<b>H80959-00</b> 11141-60A00 76 Ø 	
1,6 G16B	68-72 kW (92-98 PS)	ALTO BALENO GRAND VITARA SWIFT VITARA X-90	03/89→	<b>S40014-00</b> <sup>12</sup> <sup>13</sup> 11400-71812 <b>D40014-00</b> <sup>12</sup> 11100-58810	<b>H40014-00</b> 11141-71C00 76 Ø 	

⑩ junta, carcasa de colector de admisión / Dichtung Ansaugkrümmergehäuse / gasket, intake manifold housing / joint d'étanchéité, carter de collecteur d'admission / guarnizione, alloggiam. collettore aspirazione / прокладка, корпус впускного коллектора



<b>X83035-01</b> NBR 	<b>N92983-00</b> <b>P76779-00</b> 8x 	<b>W88317-01</b> 4x 	<b>X81696-01</b> 	<b>731414</b> 	<b>P77361-01</b> K ← 40x55x6,4 A SL RD PTFE ACM <b>P77362-01</b> K → 85x105x8,8 A SL LD PTFE ACM <b>P77668-01</b> N 27x47x7 A SL RD PTFE ACM
<b>X53956-01</b> 	<b>N92991-00</b> <b>P76662-00</b> 8x 		<b>X81077-01</b> 	<b>X54674-01</b> → 040329  <b>X54666-01</b> → 040330→	<b>P77412-01</b> K ← 35x47x7 A SL RD <b>P77296-01</b> K → 80x100x9 LD PTFE <b>P77154-01</b> N 28x42x5 RD FPM
<b>X83316-01</b> 11189-54GE0 	<b>N90112-00</b> 09289-05012-000 (16x)	<b>X89959-01</b> 13119-86G00 	<b>X81988-01</b> 14140-69G01 	<b>731414</b> 	<b>P77453-01</b> K ← 09283-41001 41x53x6 FPM <b>P77454-01</b> K → 09283-83001 83,5x103x8 FPM
<b>X83231-01</b> 11189-82600 	<b>N93015-01</b> 09289-070005-000 (8x)	<b>X89653-01</b> 13119-60A00 	<b>X82184-01</b> 14140-60A20 	<b>731414</b> 	<b>P77581-01</b> K ← 09283-41001 32x47x6 A SL RD MVQ <b>P77505-01</b> K → 09283-68001 68x86x8 A SL LD MVQ <b>P77582-01</b> N 09283-32016 32x47x8 A SL RD NBR
<b>X83269-01</b> 	<b>N90112-00</b> 09289-05012-000 (16x)	<b>X89707-01</b>  <b>X89830-01</b> <sup>10</sup> 	<b>X82229-01</b> 14140-52G00-000  <b>X82324-01</b> <sup>10</sup> 	<b>731414</b> 	<b>P77581-01</b> K ← 09283-32026 32x47x6 A SL RD MVQ <b>P77505-01</b> K → 09283-68001 68x86x8 A SL LD MVQ <b>P77581-01</b> N 09283-32026 32x47x6 A SL RD MVQ



SUZUKI						
Ltr.						
1,6 M16A	73-79 kW (99-107 PS) GRAND VITARA JIMNY LIANA SX4	04/02→	<b>D36974-01</b> ⑫ 11400-69853	<b>H80735-00</b> 11141-69G03 MLS 		
1,6 9HX	66 kW (90 PS) SX4	04/07→	<b>S36730-00</b> ⑫ ⑬  <b>D36730-00</b> ⑫  <b>B36724-00</b> ⑬	<b>H08130-00</b> 1,25 mm 2 MLS <b>H08130-10</b> 1,3 mm 3 MLS <b>H08130-20</b> 1,35 mm 1 MLS <b>H18130-30</b> 1,4 mm 4 MLS <b>H18130-40</b> 1,45 mm 5 MLS 	<b>T08130-00</b> 	
1,8 G18 J18A	89 kW (121 PS) BALENO	03/96-05/02	<b>D40040-01</b> ⑫ 11401-77862-000	<b>H40040-00</b> 11141-21111-000 MLS 		
1,9 XUD9 XUD9A	46-50 kW (63-68 PS) SAMURAI TD VITARA D	01/95→	<b>S30527-00</b> ⑫ ⑬  <b>D30527-00</b> ⑫  <b>B30527-00</b> ⑬	<b>H07781-00</b> 1,58 mm <b>H17781-10</b> 1,7 mm  <b>H05876-00</b> 1,36 mm 1 <b>H05876-10</b> 1,4 mm 2 <b>H05876-20</b> 1,44 mm 3 <b>H15876-30</b> 1,48 mm 4 <b>H15876-40</b> 1,53 mm 5 	<b>T08280-00</b> 	



<b>X83129-01</b> 11189-54G00 	<b>N90112-00</b> 09289-05012-000 (16x)	<b>X89779-01</b> 13119-69G00 	<b>X81988-01</b> 14140-69G01 	<b>731414</b> 	<b>P77453-01 K</b> ← 09283-41001 41x53x6 FPM <b>P77454-01 K</b> → 09283-83001 83,5x103x8 FPM
<b>X83038-01</b> 	<b>N93118-00</b> <b>P76780-00</b> 16x	<b>W88321-01</b> 4x  <b>W88322-01</b> 4x 	<b>X81696-01</b> 	<b>731414</b> 	<b>P77361-01 K</b> ← 40x55x6,4 A SL RD PTFE ACM <b>P77362-01 K</b> → 85x105x8,8 A SL LD PTFE ACM <b>P77668-01 N</b> 27x47x7 A SL RD PTFE ACM
<b>X83285-01</b> 11189-77E00-000 	<b>N92012-01</b> 09289-06003-000 (16x)	<b>X89729-01</b> 13119-77EA0-000 	<b>X82257-01</b> 14140-65D01-000 	<b>731414</b> 	<b>P77581-01 N</b> 09283-32026 32x47x6 A SL RD MVQ
<b>X07796-01</b> 	<b>N90300-00</b> <b>P76531-00</b> 8x	<b>X55498-01</b> 2x  <b>X55499-01</b> 	<b>X07782-01</b> 2x  <b>X03013-01</b>	<b>X07793-01</b> 	<b>P76151-01 K</b> ← 42x62x7 A RD FPM <b>P76386-01 K</b> → 90x110x7 A SL LD FPM <b>P76099-11 N</b> 35x50x8 A SL WD FPM



SUZUKI						
Ltr.						
1,9 XUD9SD	55 kW (75 PS) VITARA D	08/96-03/99	<b>S31582-00</b> <sup>12</sup> <sup>13</sup>  <b>D31582-00</b>  <b>B31582-00</b> <sup>13</sup>	<b>H02360-00</b> 1,65 mm <b>H12360-10</b> 1,75 mm  <b>H05877-00</b> 1,36 mm 1 MLS <b>H05877-10</b> 1,4 mm 2 MLS <b>H05877-20</b> 1,44 mm 3 MLS <b>H15877-30</b> 1,48 mm 4 MLS <b>H15877-40</b> 1,53 mm 5 MLS 	<b>T02360-00</b> 	
2,0 H 20 A	100 kW (136 PS) VITARA V6	12/94-03/98	<b>S40015-00</b> <sup>12</sup> <sup>13</sup> <b>D40015-00</b> <sup>12</sup>	<b>H40015-00</b> L 79 Ø  <b>H40016-00</b> R 79 Ø 		
2,0 J20A	94-107 kW (128-146 PS) GRAND VITARA SX4 VITARA	12/96→	<b>D40040-00</b> <sup>12</sup> 11400-65862-000	<b>H40040-00</b> 11141-21111-000 MLS 		
2,0 RF	52-64 kW (71-87 PS) GRAND VITARA TD VITARA TD	12/94→	<b>S40029-00</b> <sup>12</sup> <sup>13</sup> <b>D40029-00</b> <sup>12</sup>	<b>H40029-00</b> 87,6 Ø MLS 		

⑦ junta para múltiple de admisión/de escape / Dichtung Ansaug-/Abgaskrümmer / intake/exhaust manifold gasket / joint collecteur d'admission/d'échappement / guarnizione collettore di aspirazione/di scarico / прокладка всасывающего/выпускного колена



<b>X07796-01</b> 	<b>N90300-00</b> <b>P76531-00</b> 8x	<b>X03013-01</b> <sup>7</sup>  <b>X51239-01</b> <sup>7</sup> 	<b>X07793-01</b> 	<b>P76151-01</b> K ← 42x62x7 A RD FPM <b>P76386-01</b> K → 90x110x7 A SL LD FPM <b>P76099-11</b> N 35x50x8 A SL WD FPM	
<b>X83270-01</b> R 11176-85FA0  <b>X83271-01</b> L 11186-85FA0 	<b>N92012-03</b> 09289-06003 (24x)	<b>X89708-01</b> 2x  <b>X82230-01</b> 2x 	<b>731414</b> 	<b>P77483-01</b> K ← 25x35x6 A SL RD NBR <b>P77580-01</b> N 32x46x6 A SL RD MVQ	
<b>X83285-01</b> 11189-77E00-000 	<b>N92012-01</b> 09289-06003-000 (16x)	<b>X89729-01</b> 13119-77EA0-000  <b>X82251-01</b> 11140-65D01-000 	<b>731414</b> 	<b>P77581-01</b> N 09283-32026 32x47x6 A SL RD MVQ	
<b>X83198-01</b> 	<b>N93001-00</b>	<b>X89630-01</b>  <b>X82153-01</b> 	<b>X54866-01</b> 	<b>P77584-01</b> K ← 34x48x7 A SL RD NBR <b>P77529-01</b> K → 90x110x9 A SL LD NBR <b>P77584-01</b> N ← 34x48x7 A SL RD NBR	



SUZUKI						
Ltr.						
2,0 RHW	80 kW (109 PS) GRAND VITARA HDI	07/01→	1	 <b>S36517-00</b> ⑫ ⑬  <b>D36517-00</b> ⑫  <b>B36517-00</b> ⑬	<b>H01900-00</b> 1,25 mm MLS <b>H11900-10</b> 1,3 mm MLS <b>H21900-20</b> 1,35 mm MLS <b>H31900-30</b> 1,4 mm MLS 	<b>T17586-00</b> 
2,0 RHZ	80 kW (109 PS) GRAND VITARA HDI ESCUDO	07/01→		 <b>S36550-00</b> ⑫ ⑬  <b>D36550-00</b> ⑫  <b>B32989-00</b> ⑬	<b>H05133-00</b> 1,35 mm 2 MLS <b>H05133-10</b> 1,3 mm 1 MLS <b>H05133-20</b> 1,4 mm 3 MLS <b>H15133-30</b> 1,45 mm 4 MLS <b>H15133-40</b> 1,5 mm 5 MLS 	<b>T05133-00</b> 
2,0 XUD9TE	64 kW (87 PS) VITARA TD	12/95-03/98		 <b>S30527-00</b> ⑫ ⑬  <b>D30527-00</b> ⑫  <b>B30527-00</b> ⑬	<b>H02360-00</b> 1,65 mm <b>H12360-10</b> 1,75 mm  <b>H05877-00</b> 1,36 mm 1 MLS <b>H05877-10</b> 1,4 mm 2 MLS <b>H05877-20</b> 1,44 mm 3 MLS <b>H15877-30</b> 1,48 mm 4 MLS <b>H15877-40</b> 1,53 mm 5 MLS 	<b>T02360-00</b> 



<b>X53953-01</b> 	<b>N92635-00</b> <b>P76698-00</b> 16x 		<b>X81070-01</b> 	<b>731414</b> 	<b>P76151-01 K</b> ← 42x62x7 A RD FPM <b>P76386-01 K</b> → 90x110x7 A SL LD FPM <b>P77142-01 N</b> 27x47x7 A SL RD FPM
<b>X53885-01</b> 	<b>N92991-00</b> →08331 <b>N92635-00</b> →08332→ <b>P76662-00</b> →08331 <b>P76698-00</b> →08332→ 8x 8x	<b>X58968-01</b> 	<b>X52326-01</b> 	<b>731414</b> 	<b>P76151-01 K</b> ← 42x62x7 A RD FPM <b>P76386-01 K</b> → 90x110x7 A SL LD FPM <b>P77142-01 N</b> 27x47x7 A SL RD FPM
<b>X07796-01</b> 	<b>N90300-00</b> <b>P76531-00</b> 8x	<b>X55498-01</b> 2x  <b>X55499-01</b> 	<b>X07782-01</b> 2x  <b>X03013-01</b> 	<b>X07793-01</b> 	<b>P76151-01 K</b> ← 42x62x7 A RD FPM <b>P76386-01 K</b> → 90x110x7 A SL LD FPM <b>P76099-11 N</b> 35x50x8 A SL WD FPM



SUZUKI

SUZUKI													
Ltr.													
2,5 H 25 A	106-116 kW (144-158 PS)	GRAND VITARA V6	04/98→	<b>D40088-00</b> ⑫ 11400-65874	<b>H40088-00</b> L 11142-86FA1 85 Ø 1,3 mm 	<b>H40089-00</b> R 11142-86FA1 85 Ø 1,3 mm 	<b>X83270-01</b> R 11176-85FA0 	<b>X83271-01</b> L 11186-85FA0 	<b>N92012-03</b> 09289-06003 (24x)	<b>X89708-01</b> 2x 	<b>X82299-01</b> 2x 14140-67D03 	<b>731414</b> 	<b>P77560-01</b> K ← 09283-45012 45x63x7,5 A SL RD NBR <b>P77559-01</b> K → 09283-98002 98x116x10 A SL LD NBR <b>P77580-01</b> N 2x 32x46x6 A SL RD MVQ
2,7 H 27 A	127-135 kW (173-184 PS)	GRAND VITARA V6	06/01→	<b>D40086-00</b> ⑫ 11400-52823	<b>H40086-00</b> R 11141-52D01 89,5 Ø 0,7 mm MLS 	<b>H40087-00</b> L 11142-52D01 89,5 Ø 0,7 mm MLS 	<b>X83270-01</b> R 11176-85FA0 	<b>X83271-01</b> L 11186-85FA0 	<b>N92012-03</b> 09289-06003 (24x)	<b>X89708-01</b> 2x 	<b>X82299-01</b> 2x 14140-67D03 	<b>731414</b> 	<b>P77560-01</b> K ← 09283-45012 45x63x7,5 A SL RD NBR <b>P77559-01</b> K → 09283-98002 98x116x10 A SL LD NBR <b>P77580-01</b> N 2x 32x46x6 A SL RD MVQ

