



LADA

LADA

 Code 

B

BA3 2101 584

BA3 21011 584

BA3 2103 584

BA3 2103 (KAT) 584

BA3 2105 584

BA3 2106 586

BA3 2108 584

BA3 2108 (KAT) 584

BA3 21081 584

BA3 21081 (KAT) 584

BA3 21083 586

BA3 21083 (KAT) 586

BA3 2121 586

BA3 2121 (KAT) 586

C

C 20 XE 588

X

XUD9A 586

XUD9SD 586


 Code 


 Code 

 Code 

 Code 

 Code 

 Code 

 Code 

| LADA | | | | | | |
|---|------------------------|---|--------|--|----------|---------------------------------------|
| Ltr. | | | | | | |
| 1,1 BA3 21081 BA3 21081 (KAT) | 39-43 kW (53-58 PS) | SAMARA | 02/88→ | S31162-00 2900-4705 D31162-00 2900-4707 | ⑫ ⑬ ⑫ | H08634-00 2108-1003020 |
| 1,2 BA3 2101 | 44 kW (60 PS) | NOVA 1200-1500 1200-1600 | 01/70→ | S30963-00 2101-100001 D30963-00 2900-4703 | ⑫ ⑬ ⑫ | H01731-00 2101-1003020 |
| 1,3 BA3 21011 BA3 2108 BA3 2108 (KAT) | 45-48 kW (61-65 PS) | SAMARA 1200-1600 | 05/78→ | S31162-00 2900-4705 D31162-00 2900-4707 | ⑫ ⑬ ⑫ | H08634-00 2108-1003020 |
| 1,3 BA3 2105 | 48-51 kW (65-69 PS) | NOVA TOSCANA 1200-1600 | 08/74→ | S30782-00 +2101-1005034 D30782-00 | ⑫ ⑬ ⑫ | H09226-00 21011-1003020 |
| 1,4 BA3 2103 | 54-55 kW (73-75 PS) | NOVA TOSCANA 1200-1500 1200-1600 | 09/72→ | S30963-00 2101-100001 D30963-00 2900-4703 | ⑫ ⑬ ⑫ | H01731-00 2101-1003020 |
| 1,5 BA3 2103 (KAT) | 49 kW (67 PS) | NOVA | 08/94→ | S30963-00 2101-100001 D30963-00 2900-4703 | ⑫ ⑬ ⑫ | H01731-00 2101-1003020 |

⑦ junta para múltiple de admisión/de escape / Dichtung Ansaug-/Abgaskrümmer / intake/exhaust manifold gasket / joint collecteur d'admission/d'échappement / guarnizione collettore di aspirazione/di scarico / прокладка всасывающего/выпускного колена



| | | | | |
|--------------------------------------|---|------------------------------|--------------------------------------|---|
| X08964-01 2108-1003270 | N90300-00 2101-1007026 (8x) P76531-00 2101-1007026 8x | X04968-01 ⑦ 2x | X08633-01 2108-1009070 | P76045-01 K ← 2108-1005040 28x42x7 RD FPM P76338-11 K → 80x100x10 LD FPM P76045-01 N 2108-1005040 28x42x7 RD FPM |
| X09240-01 2101-1003270 | N90300-00 2101-1007026 (8x) P76531-00 2101-1007026 8x | X04968-01 ⑦ 2x | X09249-01 2101-1009070 | P76117-01 K ← 2101-1005034 40x56x7 RD P76303-01 K → 70x90x10 LD |
| X08964-01 2108-1003270 | N90300-00 2101-1007026 (8x) P76531-00 2101-1007026 8x | X04968-01 ⑦ 2x | X08633-01 2108-1009070 | P76045-01 K ← 2108-1005040 28x42x7 RD FPM P76338-11 K → 80x100x10 LD FPM P76045-01 N 2108-1005040 28x42x7 RD FPM |
| X09240-01 2101-1003270 | N90300-00 2101-1007026 (8x) P76531-00 2101-1007026 8x | X04968-01 ⑦ 2x | X09249-01 2101-1009070 | P76117-01 K ← 2101-1005034 40x56x7 RD P76303-01 K → 70x90x10 LD |
| X09240-01 2101-1003270 | N90300-00 2101-1007026 (8x) P76531-00 2101-1007026 8x | X04968-01 ⑦ 2x | X09249-01 2101-1009070 | P76117-01 K ← 2101-1005034 40x56x7 RD P76303-01 K → 70x90x10 LD |
| X09240-01 2101-1003270 | N90300-00 2101-1007026 (8x) P76531-00 2101-1007026 8x | X04968-01 ⑦ 2x | X09249-01 2101-1009070 | P76117-01 K ← 2101-1005034 40x56x7 RD P76303-01 K → 70x90x10 LD |



| LADA | | | | | | | |
|------|--|------------------------|---------------------------|--------|--|---|----------------------|
| Ltr. | | | | | | | |
| 1,5 | BA3 21083 BA3 21083 (KAT) | 50-53 kW (68-72 PS) | NOVA SAMARA | 01/88→ | S31362-00 ⑫ ⑬ 2900-4706 D31362-00 ⑫ 2900-4708 | H50120-00 21083-1003020 | |
| 1,6 | BA3 2106 BA3 2121 BA3 2121 (KAT) | 51-57 kW (69-78 PS) | NIVA NOVA 1200-1600 | 12/76→ | S30782-00 ⑫ ⑬ +2101-1005034 D30782-00 ⑫ | H09226-00 21011-1003020 | |
| 1,9 | XUD9A | 47 kW (64 PS) | NIVA D | 01/93→ | S30527-00 ⑫ ⑬ 95602514 D30527-00 ⑫ B30527-00 ⑬ | H07781-00 1,58 mm H17781-10 1,7 mm H05876-00 1,36 mm 1 H05876-10 1,4 mm 2 H05876-20 1,44 mm 3 H15876-30 1,48 mm 4 H15876-40 1,53 mm 5 | T08280-00 |
| 1,9 | XUD9SD | 55 kW (75 PS) | NIVA D | 01/99→ | S31582-00 ⑫ ⑬ D31582-00 B31582-00 ⑬ | H02360-00 1,65 mm H12360-10 1,75 mm H05877-00 1,36 mm 1 MLS H05877-10 1,4 mm 2 MLS H05877-20 1,44 mm 3 MLS H15877-30 1,48 mm 4 MLS H15877-40 1,53 mm 5 MLS | T02360-00 |


⑦ junta para múltiple de admisión/de escape / Dichtung Ansaug-/Abgaskrümmer / intake/exhaust manifold gasket / joint collecteur d'admission/d'échappement / guarnizione collettore di aspirazione/di scarico / прокладка всасывающего/выпускного колена



| | | | | | |
|--------------------------------------|---|---|---|--------------------------------------|---|
| X08964-01 2108-1003270 | N90300-00 2101-1007026 (8x) P76531-00 2101-1007026 8x | X08948-01 ⑦ 2x 21083-1008081 | X04968-01 ⑦ | X08633-01 2108-1009070 | P76045-01 K ← 2108-1005040 28x42x7 RD FPM P76338-11 K → 80x100x10 LD FPM P76045-01 N 2108-1005040 28x42x7 RD FPM |
| X09240-01 2101-1003270 | N90300-00 2101-1007026 (8x) P76531-00 2101-1007026 8x | X09241-01 ⑦ 2x 2101-1008081 | X04968-01 ⑦ | X09249-01 2101-1009070 | P76117-01 K ← 2101-1005034 40x56x7 RD P76303-01 K → 70x90x10 LD |
| X07796-01 | N90300-00 2101-1007026 (8x) P76531-00 2101-1007026 8x | X55498-01 2x X55499-01 | X07782-01 2x X03013-01 ⑦ | E30527-00 | P76151-01 K ← 42x62x7 A RD FPM P76386-01 K → 90x110x7 A SL LD FPM P76099-11 N 35x50x8 A SL WD FPM |
| X07796-01 | N90300-00 2101-1007026 (8x) P76531-00 2101-1007026 8x | X51239-01 ⑦ | X03013-01 ⑦ | X07793-01 | P76151-01 K ← 42x62x7 A RD FPM P76386-01 K → 90x110x7 A SL LD FPM P76099-11 N 35x50x8 A SL WD FPM |



| | | | | | | | | | | |
|---|--|--|----------------------|---|-----------------------------|---|----------------------|--|-------------------------|--|
| LADA Ltr. 2,0 C 20 XE 110 kW (150 PS) 110 08/96→ | | | | | | | | | | |
| 1 2,0 C 20 XE 110 kW (150 PS) 110 08/96→ | | S31189-00 ⑫ ⑬ D31189-00 ⑫ B31189-00 ⑬ | H07938-00 | T07938-00 → 14137011 T50466-00 → 14137012→ | X07933-01 NBR | N92310-00 2x P76601-00 16x 90215296 | X07936-01 | X07937-01 X51027-01 | X54120-01 2x | P76130-01 K ← 38x50x8 RD FPM P76384-01 K → 90x104x9/11 AB SL LD FPM P76095-01 N 2x 35x48x7 RD |



LADA